Tool ID: 1802 Tool Location: 224

Equipment Information Sheet

Hot Press (2nd Floor)

Manager:Sam Wright
Backup:607-254-4836
John TreichlerCalls to staff phones will be automatically forwarded to their cell phones during
accessible hours. At other times leave a message or send them an email.

SAFETY

• User must place shield with (CAUTION MAY BE HOT) sign over the press before leaving, even if the press is not hot.

USAGE RESTRICTIONS SCHEDULING/SIGN-UP RESTRICTIONS

None

Minimum Tool Time: 60 minutes

MATERIALS COMPATIBILITY CATEGORY

Tool Category 5: Class A and B Metals and Compounds	
Allowed	Not Allowed
Tool category 1/1E, 2, 3, and 4 materials	
Silicon Based Substrates and Films	
III/V compound Semiconductors	
Glass Substrates	
PECVD and ALD Films	
Cured organics and baked Photoresist	
CNF Class A, B, and Refractory metals	
Exposed Gold, Silver, Copper	
Alkali and Alkaline Compounds	
Organic/Biology Molecules prepared-w/salt buffers	
High Vapor Pressure Materials (Mg, Ca, Zn)*	* Some tool restrictions on high vapor pressure materials may apply
Soft organic materials	

High Vapor Pressure Metals and Compounds are materials that have a vapor pressure above 1e-6 Torr at 400 C.

Additional Material Restrictions and Exceptions

• Do not place plastics directly on hot surfaces. Use glass slides or wafers to protect plastic from melting directly on the hotpress surface.

Last Updated: 04/25/2019