Tool ID: 428 Tool Location: 121

Equipment Information Sheet

UV Curing Station

Manager: Roberto Panepucci Backup: Giovanni Sartorello 607-254-4855 607-254-4853 Calls to staff phones will be automatically forwarded to their cell phones during accessible hours. At other times leave a message or send them an email.

SAFETY

• Do not Lift UV Curing Box while ON!

• Turn it OFF to take your sample out!

• Use handle to lift after finished. It can be HOT!

USAGE RESTRICTIONS
SCHEDULING/SIGN-UP RESTRICTIONS
MATERIALS COMPATIBILITY CATEGORY

Minimum Tool Time: 0 minutes

Additional Material Restrictions and Exceptions

Last Updated: 02/13/2024